

# TABLE OF CONTENTS

-----  
VOLUME ONE

SECTION A  
-----

DISCLAIMER  
ABSTRACT  
TABLE OF CONTENTS  
METHOD INDEX AND CONVERSION TABLE  
PREFACE  
ACKNOWLEDGEMENTS

---

## PART I METHODS FOR ANALYTES AND PROPERTIES

### CHAPTER ONE -- QUALITY CONTROL

- 1.0 Introduction
- 2.0 QA Project Plan
- 3.0 Field Operations
- 4.0 Laboratory Operations
- 5.0 Definitions
- 6.0 References

### CHAPTER TWO -- CHOOSING THE CORRECT PROCEDURE

- 2.1 Purpose
- 2.2 Required Information
- 2.3 Implementing the Guidance
- 2.4 Characteristics
- 2.5 Ground Water
- 2.6 References

### CHAPTER THREE -- INORGANIC ANALYTES

- 3.1 Sampling Considerations
- 3.2 Sample Preparation Methods

<b>Method 3005A:</b>	Acid Digestion of Waters for Total Recoverable or Dissolved Metals for Analysis by FLAA or ICP Spectroscopy
<b>Method 3010A:</b>	Acid Digestion of Aqueous Samples and Extracts for Total Metals for Analysis by FLAA or ICP Spectroscopy
<b>Method 3015:</b>	Microwave Assisted Acid Digestion of Aqueous Samples and Extracts
<b>Method 3020A:</b>	Acid Digestion of Aqueous Samples and Extracts for Total Metals for Analysis by GFAA Spectroscopy
<b>Method 3031:</b>	Acid Digestion of Oils for Metals Analysis by Atomic Absorption or ICP Spectrometry
<b>Method 3040A:</b>	Dissolution Procedure for Oils, Greases, or Waxes
<b>Method 3050B:</b>	Acid Digestion of Sediments, Sludges, and Soils

<b>Method 3051:</b>	Microwave Assisted Acid Digestion of Sediments, Sludges, Soils, and Oils
<b>Method 3052:</b>	Microwave Assisted Acid Digestion of Siliceous and Organically Based Matrices
<b>Method 3060A:</b>	Alkaline Digestion for Hexavalent Chromium

### 3.3 Methods for Determination of Inorganic Analytes

<b>Method 6010B:</b>	Inductively Coupled Plasma-Atomic Emission Spectrometry
<b>Method 6020:</b>	Inductively Coupled Plasma-Mass Spectrometry
<b>Method 7000A:</b>	Atomic Absorption Methods
<b>Method 7020:</b>	Aluminum (Atomic Absorption, Direct Aspiration)
<b>Method 7040:</b>	Antimony (Atomic Absorption, Direct Aspiration)
<b>Method 7041:</b>	Antimony (Atomic Absorption, Furnace Technique)
<b>Method 7060A:</b>	Arsenic (Atomic Absorption, Furnace Technique)
<b>Method 7061A:</b>	Arsenic (Atomic Absorption, Gaseous Hydride)
<b>Method 7062:</b>	Antimony and Arsenic (Atomic Absorption, Borohydride Reduction)
<b>Method 7063:</b>	Arsenic in Aqueous Samples and Extracts by Anodic Stripping Voltammetry (ASV)
<b>Method 7080A:</b>	Barium (Atomic Absorption, Direct Aspiration)
<b>Method 7081:</b>	Barium (Atomic Absorption, Furnace Technique)
<b>Method 7090:</b>	Beryllium (Atomic Absorption, Direct Aspiration)
<b>Method 7091:</b>	Beryllium (Atomic Absorption, Furnace Technique)
<b>Method 7130:</b>	Cadmium (Atomic Absorption, Direct Aspiration)
<b>Method 7131A:</b>	Cadmium (Atomic Absorption, Furnace Technique)
<b>Method 7140:</b>	Calcium (Atomic Absorption, Direct Aspiration)
<b>Method 7190:</b>	Chromium (Atomic Absorption, Direct Aspiration)
<b>Method 7191:</b>	Chromium (Atomic Absorption, Furnace Technique)
<b>Method 7195:</b>	Chromium, Hexavalent (Coprecipitation)
<b>Method 7196A:</b>	Chromium, Hexavalent (Colorimetric)
<b>Method 7197:</b>	Chromium, Hexavalent (Chelation/Extraction)
<b>Method 7198:</b>	Chromium, Hexavalent (Differential Pulse Polarography)
<b>Method 7199:</b>	Determination of Hexavalent Chromium in Drinking Water, Groundwater and Industrial Wastewater Effluents by Ion Chromatography
<b>Method 7200:</b>	Cobalt (Atomic Absorption, Direct Aspiration)
<b>Method 7201:</b>	Cobalt (Atomic Absorption, Furnace Technique)
<b>Method 7210:</b>	Copper (Atomic Absorption, Direct Aspiration)
<b>Method 7211:</b>	Copper (Atomic Absorption, Furnace Technique)
<b>Method 7380:</b>	Iron (Atomic Absorption, Direct Aspiration)
<b>Method 7381:</b>	Iron (Atomic Absorption, Furnace Technique)
<b>Method 7420:</b>	Lead (Atomic Absorption, Direct Aspiration)
<b>Method 7421:</b>	Lead (Atomic Absorption, Furnace Technique)
<b>Method 7430:</b>	Lithium (Atomic Absorption, Direct Aspiration)
<b>Method 7450:</b>	Magnesium (Atomic Absorption, Direct Aspiration)
<b>Method 7460:</b>	Manganese (Atomic Absorption, Direct Aspiration)
<b>Method 7461:</b>	Manganese (Atomic Absorption, Furnace Technique)
<b>Method 7470A:</b>	Mercury in Liquid Waste (Manual Cold-Vapor Technique)

<b>Method 7471A:</b>	Mercury in Solid or Semisolid Waste (Manual Cold-Vapor Technique)
<b>Method 7472:</b>	Mercury in Aqueous Samples and Extracts by Anodic Stripping Voltammetry (ASV)
<b>Method 7480:</b>	Molybdenum (Atomic Absorption, Direct Aspiration)
<b>Method 7481:</b>	Molybdenum (Atomic Absorption, Furnace Technique)
<b>Method 7520:</b>	Nickel (Atomic Absorption, Direct Aspiration)
<b>Method 7521:</b>	Nickel (Atomic Absorption, Furnace Method)
<b>Method 7550:</b>	Osmium (Atomic Absorption, Direct Aspiration)
<b>Method 7580:</b>	White Phosphorus (P <sub>4</sub> ) by Solvent Extraction and Gas Chromatography
<b>Method 7610:</b>	Potassium (Atomic Absorption, Direct Aspiration)
<b>Method 7740:</b>	Selenium (Atomic Absorption, Furnace Technique)
<b>Method 7741A:</b>	Selenium (Atomic Absorption, Gaseous Hydride)
<b>Method 7742:</b>	Selenium (Atomic Absorption, Borohydride Reduction)
<b>Method 7760A:</b>	Silver (Atomic Absorption, Direct Aspiration)
<b>Method 7761:</b>	Silver (Atomic Absorption, Furnace Technique)
<b>Method 7770:</b>	Sodium (Atomic Absorption, Direct Aspiration)
<b>Method 7780:</b>	Strontium (Atomic Absorption, Direct Aspiration)
<b>Method 7840:</b>	Thallium (Atomic Absorption, Direct Aspiration)
<b>Method 7841:</b>	Thallium (Atomic Absorption, Furnace Technique)
<b>Method 7870:</b>	Tin (Atomic Absorption, Direct Aspiration)
<b>Method 7910:</b>	Vanadium (Atomic Absorption, Direct Aspiration)
<b>Method 7911:</b>	Vanadium (Atomic Absorption, Furnace Technique)
<b>Method 7950:</b>	Zinc (Atomic Absorption, Direct Aspiration)
<b>Method 7951:</b>	Zinc (Atomic Absorption, Furnace Technique)

## APPENDIX -- COMPANY REFERENCES

**NOTE:** A suffix of "A" in the method number indicates revision one (the method has been revised once). A suffix of "B" in the method number indicates revision two (the method has been revised twice). A suffix of "C" in the method number indicates revision three (the method has been revised three times), etc. **In order to properly document the method used for analysis, the entire method number including the suffix letter designation (e.g., A, B, C or D) must be identified by the analyst.** A method reference found within the RCRA regulations and the text of SW-846 methods and chapters refers to the latest final revision of the method, even if the method number does not include the appropriate letter suffix.

-----  
VOLUME ONE

SECTION B  
-----

DISCLAIMER

ABSTRACT

TABLE OF CONTENTS

METHOD INDEX AND CONVERSION TABLE

PREFACE

ACKNOWLEDGEMENTS

CHAPTER ONE, REPRINTED -- QUALITY CONTROL

- 1.0 Introduction
- 2.0 QA Project Plan
- 3.0 Field Operations
- 4.0 Laboratory Operations
- 5.0 Definitions
- 6.0 References

CHAPTER FOUR -- ORGANIC ANALYTES

- 4.1 Sampling Considerations
- 4.2 Sample Preparation Methods

4.2.1 Extractions and Preparations

<b>Method 3500B:</b>	Organic Extraction and Sample Preparation
<b>Method 3510C:</b>	Separatory Funnel Liquid-Liquid Extraction
<b>Method 3520C:</b>	Continuous Liquid-Liquid Extraction
<b>Method 3535:</b>	Solid-Phase Extraction (SPE)
<b>Method 3540C:</b>	Soxhlet Extraction
<b>Method 3541:</b>	Automated Soxhlet Extraction
<b>Method 3542:</b>	Extraction of Semivolatile Analytes Collected Using Method 0010 (Modified Method 5 Sampling Train)
<b>Method 3545:</b>	Pressurized Fluid Extraction (PFE)
<b>Method 3550B:</b>	Ultrasonic Extraction
<b>Method 3560:</b>	Supercritical Fluid Extraction of Total Recoverable Petroleum Hydrocarbons
<b>Method 3561:</b>	Supercritical Fluid Extraction of Polynuclear Aromatic Hydrocarbons
<b>Method 3580A:</b>	Waste Dilution
<b>Method 3585:</b>	Waste Dilution for Volatile Organics
<b>Method 5000:</b>	Sample Preparation for Volatile Organic Compounds
<b>Method 5021:</b>	Volatile Organic Compounds in Soils and Other Solid Matrices Using Equilibrium Headspace Analysis

<b>Method 5030B:</b>	Purge-and-Trap for Aqueous Samples
<b>Method 5031:</b>	Volatile, Nonpurgeable, Water-Soluble Compounds by Azeotropic Distillation
<b>Method 5032:</b>	Volatile Organic Compounds by Vacuum Distillation
<b>Method 5035:</b>	Closed-System Purge-and-Trap and Extraction for Volatile Organics in Soil and Waste Samples
<b>Method 5041A:</b>	Analysis for Desorption of Sorbent Cartridges from Volatile Organic Sampling Train (VOST)

#### 4.2.2 Cleanup

<b>Method 3600C:</b>	Cleanup
<b>Method 3610B:</b>	Alumina Cleanup
<b>Method 3611B:</b>	Alumina Column Cleanup and Separation of Petroleum Wastes
<b>Method 3620B:</b>	Florisil Cleanup
<b>Method 3630C:</b>	Silica Gel Cleanup
<b>Method 3640A:</b>	Gel-Permeation Cleanup
<b>Method 3650B:</b>	Acid-Base Partition Cleanup
<b>Method 3660B:</b>	Sulfur Cleanup
<b>Method 3665A:</b>	Sulfuric Acid/Permanganate Cleanup

### 4.3 Determination of Organic Analytes

#### 4.3.1 Gas Chromatographic Methods

<b>Method 8000B:</b>	Determinative Chromatographic Separations
<b>Method 8011:</b>	1,2-Dibromoethane and 1,2-Dibromo-3-chloropropane by Microextraction and Gas Chromatography
<b>Method 8015B:</b>	Nonhalogenated Organics Using GC/FID
<b>Method 8021B:</b>	Aromatic and Halogenated Volatiles by Gas Chromatography Using Photoionization and/or Electrolytic Conductivity Detectors
<b>Method 8031:</b>	Acrylonitrile by Gas Chromatography
<b>Method 8032A:</b>	Acrylamide by Gas Chromatography
<b>Method 8033:</b>	Acetonitrile by Gas Chromatography with Nitrogen-Phosphorus Detection
<b>Method 8041:</b>	Phenols by Gas Chromatography
<b>Method 8061A:</b>	Phthalate Esters by Gas Chromatography with Electron Capture Detection (GC/ECD)
<b>Method 8070A:</b>	Nitrosamines by Gas Chromatography
<b>Method 8081A:</b>	Organochlorine Pesticides by Gas Chromatography
<b>Method 8082:</b>	Polychlorinated Biphenyls (PCBs) by Gas Chromatography
<b>Method 8091:</b>	Nitroaromatics and Cyclic Ketones by Gas Chromatography
<b>Method 8100:</b>	Polynuclear Aromatic Hydrocarbons
<b>Method 8111:</b>	Haloethers by Gas Chromatography
<b>Method 8121:</b>	Chlorinated Hydrocarbons by Gas Chromatography: Capillary Column Technique
<b>Method 8131:</b>	Aniline and Selected Derivatives by Gas Chromatography
<b>Method 8141A:</b>	Organophosphorus Compounds by Gas Chromatography: Capillary Column Technique

**Method 8151A:** Chlorinated Herbicides by GC Using Methylation or Pentafluorobenzoylation Derivatization

#### 4.3.2 Gas Chromatographic/Mass Spectroscopic Methods

**Method 8260B:** Volatile Organic Compounds by Gas Chromatography/Mass Spectrometry (GC/MS)

**Method 8270C:** Semivolatile Organic Compounds by Gas Chromatography/Mass Spectrometry (GC/MS)

**Method 8275A:** Semivolatile Organic Compounds (PAHs and PCBs) in Soils/Sludges and Solid Wastes Using Thermal Extraction/Gas Chromatography/Mass Spectrometry (TE/GC/MS)

**Method 8280A:** The Analysis of Polychlorinated Dibenzo-*p*-Dioxins and Polychlorinated Dibenzofurans by High Resolution Gas Chromatography/Low Resolution Mass Spectrometry (HRGC/LRMS)

**Method 8290:** Polychlorinated Dibenzodioxins (PCDDs) and Polychlorinated Dibenzofurans (PCDFs) by High-Resolution Gas Chromatography/High-Resolution Mass Spectrometry (HRGC/HRMS)

**Attachment A:** Procedures for the Collection, Handling, Analysis, and Reporting of Wipe Tests Performed within the Laboratory

#### 4.3.3 High Performance Liquid Chromatographic Methods

**Method 8310:** Polynuclear Aromatic Hydrocarbons

**Method 8315A:** Determination of Carbonyl Compounds by High Performance Liquid Chromatography (HPLC)

**Appendix A:** Recrystallization of 2,4-Dinitrophenylhydrazine (DNPH)

**Method 8316:** Acrylamide, Acrylonitrile and Acrolein by High Performance Liquid Chromatography (HPLC)

**Method 8318:** N-Methylcarbamates by High Performance Liquid Chromatography (HPLC)

**Method 8321A:** Solvent Extractable Nonvolatile Compounds by High Performance Liquid Chromatography/Thermospray/Mass Spectrometry (HPLC/TS/MS) or Ultraviolet (UV) Detection

**Method 8325:** Solvent Extractable Nonvolatile Compounds by High Performance Liquid Chromatography/Particle Beam/Mass Spectrometry (HPLC/PB/MS)

**Method 8330:** Nitroaromatics and Nitramines by High Performance Liquid Chromatography (HPLC)

**Method 8331:** Tetrazene by Reverse Phase High Performance Liquid Chromatography (HPLC)

**Method 8332:** Nitroglycerine by High Performance Liquid Chromatography

#### 4.3.4 Infrared Methods

**Method 8410:** Gas Chromatography/Fourier Transform Infrared (GC/FT-IR) Spectrometry for Semivolatile Organics: Capillary Column

- Method 8430:** Analysis of Bis(2-chloroethyl) Ether and Hydrolysis Products by Direct Aqueous Injection GC/FT-IR
- Method 8440:** Total Recoverable Petroleum Hydrocarbons by Infrared Spectrophotometry

#### 4.3.5 Miscellaneous Spectrometric Methods

- Method 8520:** Continuous Measurement of Formaldehyde in Ambient Air

#### 4.4 Immunoassay Methods

- Method 4000:** Immunoassay
- Method 4010A:** Screening for Pentachlorophenol by Immunoassay
- Method 4015:** Screening for 2,4-Dichlorophenoxyacetic Acid by Immunoassay
- Method 4020:** Screening for Polychlorinated Biphenyls by Immunoassay
- Method 4030:** Soil Screening for Petroleum Hydrocarbons by Immunoassay
- Method 4035:** Soil Screening for Polynuclear Aromatic Hydrocarbons by Immunoassay
- Method 4040:** Soil Screening for Toxaphene by Immunoassay
- Method 4041:** Soil Screening for Chlordane by Immunoassay
- Method 4042:** Soil Screening for DDT by Immunoassay
- Method 4050:** TNT Explosives in Soil by Immunoassay
- Method 4051:** Hexahydro-1,3,5-trinitro-1,3,5-triazine (RDX) in Soil by Immunoassay

#### 4.5 Miscellaneous Screening Methods

- Method 3810:** Headspace
- Method 3820:** Hexadecane Extraction and Screening of Purgeable Organics
- Method 8515:** Colorimetric Screening Method for Trinitrotoluene (TNT) in Soil
- Method 9078:** Screening Test Method for Polychlorinated Biphenyls in Soil
- Method 9079:** Screening Test Method for Polychlorinated Biphenyls in Transformer Oil

### APPENDIX -- COMPANY REFERENCES

**NOTE:** A suffix of "A" in the method number indicates revision one (the method has been revised once). A suffix of "B" in the method number indicates revision two (the method has been revised twice). A suffix of "C" in the method number indicates revision three (the method has been revised three times), etc. **In order to properly document the method used for analysis, the entire method number including the suffix letter designation (e.g., A, B, C or D) must be identified by the analyst.** A method reference found within the RCRA regulations and the text of SW-846 methods and chapters refers to the latest final revision of the method, even if the method number does not include the appropriate letter suffix.

-----  
VOLUME ONE

SECTION C  
-----

DISCLAIMER

ABSTRACT

TABLE OF CONTENTS

METHOD INDEX AND CONVERSION TABLE

PREFACE

CHAPTER ONE, REPRINTED -- QUALITY CONTROL

- 1.0 Introduction
- 2.0 QA Project Plan
- 3.0 Field Operations
- 4.0 Laboratory Operations
- 5.0 Definitions
- 6.0 References

CHAPTER FIVE -- MISCELLANEOUS TEST METHODS

<b>Method 5050:</b>	Bomb Preparation Method for Solid Waste
<b>Method 9010C:</b>	Total and Amenable Cyanide: Distillation
<b>Method 9012B:</b>	Total and Amenable Cyanide (Automated Colorimetric, with Off-Line Distillation)
<b>Method 9013:</b>	Cyanide Extraction Procedure for Solids and Oils
<b>Method 9014:</b>	Titrimetric and Manual Spectrophotometric Determinative Methods for Cyanide
<b>Method 9020B:</b>	Total Organic Halides (TOX)
<b>Method 9021:</b>	Purgeable Organic Halides (POX)
<b>Method 9022:</b>	Total Organic Halides (TOX) by Neutron Activation Analysis
<b>Method 9023:</b>	Extractable Organic Halides (EOX) in Solids
<b>Method 9030B:</b>	Acid-Soluble and Acid-Insoluble Sulfides: Distillation
<b>Method 9031:</b>	Extractable Sulfides
<b>Method 9034:</b>	Titrimetric Procedure for Acid-Soluble and Acid-Insoluble Sulfides
<b>Method 9035:</b>	Sulfate (Colorimetric, Automated, Chloranilate)
<b>Method 9036:</b>	Sulfate (Colorimetric, Automated, Methylthymol Blue, AA II)
<b>Method 9038:</b>	Sulfate (Turbidimetric)
<b>Method 9056:</b>	Determination of Inorganic Anions by Ion Chromatography
<b>Method 9057:</b>	Determination of Chloride from HCl/Cl <sub>2</sub> Emission Sampling Train (Methods 0050 and 0051) by Anion Chromatography
<b>Method 9060A:</b>	Total Organic Carbon
<b>Method 9065:</b>	Phenolics (Spectrophotometric, Manual 4-AAP with Distillation)
<b>Method 9066:</b>	Phenolics (Colorimetric, Automated 4-AAP with Distillation)
<b>Method 9067:</b>	Phenolics (Spectrophotometric, MBTH with Distillation)
<b>Method 9070A:</b>	n-Hexane Extractable Material (HEM) for Aqueous Samples
<b>Method 9071B:</b>	n-Hexane Extractable Material (HEM) for Sludge, Sediment, and Solid Samples



<b>Method 9075:</b>	Test Method for Total Chlorine in New and Used Petroleum Products by X-Ray Fluorescence Spectrometry (XRF)
<b>Method 9076:</b>	Test Method for Total Chlorine in New and Used Petroleum Products by Oxidative Combustion and Microcoulometry
<b>Method 9077:</b>	Test Methods for Total Chlorine in New and Used Petroleum Products (Field Test Kit Methods)
<b>Method A:</b>	Fixed End Point Test Kit Method
<b>Method B:</b>	Reverse Titration Quantitative End Point Test Kit Method
<b>Method C:</b>	Direct Titration Quantitative End Point Test Kit Method
<b>Method 9131:</b>	Total Coliform: Multiple Tube Fermentation Technique
<b>Method 9132:</b>	Total Coliform: Membrane-Filter Technique
<b>Method 9210:</b>	Potentiometric Determination of Nitrate in Aqueous Samples with Ion-Selective Electrode
<b>Method 9211:</b>	Potentiometric Determination of Bromide in Aqueous Samples with Ion-Selective Electrode
<b>Method 9212:</b>	Potentiometric Determination of Chloride in Aqueous Samples with Ion-Selective Electrode
<b>Method 9213:</b>	Potentiometric Determination of Cyanide in Aqueous Samples and Distillates with Ion-Selective Electrode
<b>Method 9214:</b>	Potentiometric Determination of Fluoride in Aqueous Samples with Ion-Selective Electrode
<b>Method 9215:</b>	Potentiometric Determination of Sulfide in Aqueous Samples and Distillates with Ion-Selective Electrode
<b>Method 9250:</b>	Chloride (Colorimetric, Automated Ferricyanide AAI)
<b>Method 9251:</b>	Chloride (Colorimetric, Automated Ferricyanide AAI)
<b>Method 9253:</b>	Chloride (Titrimetric, Silver Nitrate)
<b>Method 9320:</b>	Radium-228

## CHAPTER SIX -- PROPERTIES

<b>Method 1030:</b>	Ignitability of Solids
<b>Method 1120:</b>	Dermal Corrosion
<b>Method 1312:</b>	Synthetic Precipitation Leaching Procedure
<b>Method 1320:</b>	Multiple Extraction Procedure
<b>Method 1330A:</b>	Extraction Procedure for Oily Wastes
<b>Method 9041A:</b>	pH Paper Method
<b>Method 9045D:</b>	Soil and Waste pH
<b>Method 9050A:</b>	Specific Conductance
<b>Method 9080:</b>	Cation-Exchange Capacity of Soils (Ammonium Acetate)
<b>Method 9081:</b>	Cation-Exchange Capacity of Soils (Sodium Acetate)
<b>Method 9090A:</b>	Compatibility Test for Wastes and Membrane Liners
<b>Method 9095B:</b>	Paint Filter Liquids Test
<b>Method 9096:</b>	Liquid Release Test (LRT) Procedure
<b>Appendix A:</b>	Liquid Release Test Pre-Test
<b>Method 9100:</b>	Saturated Hydraulic Conductivity, Saturated Leachate Conductivity, and Intrinsic Permeability
<b>Method 9310:</b>	Gross Alpha and Gross Beta
<b>Method 9315:</b>	Alpha-Emitting Radium Isotopes

## PART II CHARACTERISTICS

### CHAPTER SEVEN -- CHARACTERISTICS INTRODUCTION AND REGULATORY DEFINITIONS

- 7.1 Ignitability
- 7.2 Corrosivity
- 7.3 Reactivity
- 7.4 Toxicity Characteristic Leaching Procedure

### CHAPTER EIGHT -- METHODS FOR DETERMINING CHARACTERISTICS

- 8.1 Ignitability
  - Method 1010A:** Test Methods for Flash Point by Pensky-Martens Closed Cup Tester
  - Method 1020B:** Standard Test Methods for Flash Point by Setaflash (Small Scale) Closed-cup Apparatus
- 8.2 Corrosivity
  - Method 9040C:** pH Electrometric Measurement
  - Method 1110A:** Corrosivity Toward Steel
- 8.3 Toxicity
  - Method 1310B:** Extraction Procedure (EP) Toxicity Test Method and Structural Integrity Test
  - Method 1311:** Toxicity Characteristic Leaching Procedure

### APPENDIX -- COMPANY REFERENCES

**NOTE:** A suffix of "A" in the method number indicates revision one (the method has been revised once). A suffix of "B" in the method number indicates revision two (the method has been revised twice). A suffix of "C" in the method number indicates revision three (the method has been revised three times), etc. **In order to properly document the method used for analysis, the entire method number including the suffix letter designation (e.g., A, B, C or D) must be identified by the analyst.** A method reference found within the RCRA regulations and the text of SW-846 methods and chapters refers to the latest final revision of the method, even if the method number does not include the appropriate letter suffix.

-----  
VOLUME TWO  
-----

DISCLAIMER  
ABSTRACT  
TABLE OF CONTENTS  
METHOD INDEX AND CONVERSION TABLE  
PREFACE

CHAPTER ONE, REPRINTED -- QUALITY CONTROL

- 1.0 Introduction
- 2.0 QA Project Plan
- 3.0 Field Operations
- 4.0 Laboratory Operations
- 5.0 Definitions
- 6.0 References

PART III SAMPLING

CHAPTER NINE -- SAMPLING PLAN

- 9.1 Design and Development
- 9.2 Implementation

CHAPTER TEN -- SAMPLING METHODS

- Method 0010:** Modified Method 5 Sampling Train
- Appendix A:** Preparation of XAD-2 Sorbent Resin
- Appendix B:** Total Chromatographable Organic Material Analysis
- Method 0011:** Sampling for Selected Aldehyde and Ketone Emissions from Stationary Sources
- Method 0020:** Source Assessment Sampling System (SASS)
- Method 0023A:** Sampling Method for Polychlorinated Dibenzo-p-Dioxins and Polychlorinated Dibenzofuran Emissions from Stationary Sources
- Method 0030:** Volatile Organic Sampling Train
- Method 0031:** Sampling Method for Volatile Organic Compounds (SMVOC)
- Method 0040:** Sampling of Principal Organic Hazardous Constituents from Combustion Sources Using Tedlar® Bags
- Method 0050:** Isokinetic HCl/Cl<sub>2</sub> Emission Sampling Train
- Method 0051:** Midget Impinger HCl/Cl<sub>2</sub> Emission Sampling Train
- Method 0060:** Determination of Metals in Stack Emissions
- Method 0061:** Determination of Hexavalent Chromium Emissions from Stationary Sources
- Method 0100:** Sampling for Formaldehyde and Other Carbonyl Compounds in Indoor Air

## PART IV MONITORING

### CHAPTER ELEVEN -- GROUND WATER MONITORING

- 11.1 Background and Objectives
- 11.2 Relationship to the Regulations and to Other Documents
- 11.3 Revisions and Additions
- 11.4 Acceptable Designs and Practices
- 11.5 Unacceptable Designs and Practices

### CHAPTER TWELVE -- LAND TREATMENT MONITORING

- 12.1 Background
- 12.2 Treatment Zone
- 12.3 Regulatory Definition
- 12.4 Monitoring and Sampling Strategy
- 12.5 Analysis
- 12.6 References and Bibliography

### CHAPTER THIRTEEN -- INCINERATION

- 13.1 Introduction
- 13.2 Regulatory Definition
- 13.3 Waste Characterization Strategy
- 13.4 Stack-Gas Effluent Characterization Strategy
- 13.5 Additional Effluent Characterization Strategy
- 13.6 Selection of Specific Sampling and Analysis Methods
- 13.7 References

### APPENDIX -- COMPANY REFERENCES

**NOTE:** A suffix of "A" in the method number indicates revision one (the method has been revised once). A suffix of "B" in the method number indicates revision two (the method has been revised twice). A suffix of "C" in the method number indicates revision three (the method has been revised three times), etc. **In order to properly document the method used for analysis, the entire method number including the suffix letter designation (e.g., A, B, C or D) must be identified by the analyst.** A method reference found within the RCRA regulations and the text of SW-846 methods and chapters refers to the latest final revision of the method, even though the method number does not include the appropriate letter suffix.